

Tank Storage Status

Version Date: 4/12/2019 7:33

Table 1: Response Tanks Storing Collected Response Liquids

Tank #	Material Stored	Tank Max Capacity (bbls)	Current Level - Total (bbls)	Water Level (bbls)	Organic Total (bbls)	Comment/Activity
80-18	Firefighting Water/Organics	71,508	67,861	23,920	43,941	No Activity
80-33	Firefighting Water/Organics	72,528	45,280	14,730	30,550	Active via Vacuum Trucks
100-28	Firefighting Water/Organics	100,297	44,500	28,574	15,926	Active via Vacuum Trucks
100-31	Firefighting Water/Organics	100,255	99,901	90,800	9,101	No Activity
100-15	Firefighting Water/Organics	100,256	79,798	60,585	19,213	Active via Tank farm draining
100-1	Firefighting Water/Organics	100,074	12,742	0	12,742	No Activity; Ready to receive material
		544,918	350,082	218,609	131,473	

Table 2: ITC Wastewater System Tanks

Tank #	Material Stored	Tank Max Capacity (bbls)	Current Level - Total (bbls)	Water Level (bbls)	Organic Total (bbls)	Comment/Activity
50-2	Prior Wastewater/Firefighting Water/Organics	52,084	50,854	50,665	189	
80-34	Prior Wastewater/Firefighting Water/Organics	80,287	57,650	54,021	3,629	
60-1	Prior Wastewater/Firefighting Water/Organics	54,384	50,591	44,272	6,319	
		186,755	159,095	148,958	10,137	

Table 3: Temporary Storage Vessels Loaded

Barge	Prior Wastewater/Firefighting Water/Organics	57,000	49,157	49,157		
-------	--	--------	--------	--------	--	--

Table 2: Impacted Tank Farm Information

Tank #	Material Stored Prior to Event	Safe Operating Capacity (bbls)	Current Level - Total (bbls)	Quantity Prior To Event (bbls)	Comment/Activity	Physical Status Of The Tank
80-1	Base Oil	72,978	750	49,760	Small heel remaining - will complete rinse	Tank erect, charred, damage to roof
80-2	Gas Blendstock	74,189	0	42,260	COMPLETE - No Further Action Required	Collapsed
80-3	Gas Blendstock	69,679	0	33,410	COMPLETE - No Further Action Required	Tank erect, charred, but heavily damaged
80-4	Base Oil	74,497	750	35,699	Small heel remaining - will complete rinse	Tank erect, charred, damage to roof
80-5	Xylene	72,859	100	38,426	Cleaning In Progress	Collapsed
80-6	Gas Blendstock	74,789	100	49,414	COMPLETE - No Further Action Required	Collapsed
80-7	Pygas	75,373	1,000	43,595	Small heel remaining - Degas Equipment Being Installed	Half of the tank standing, roof collapsed
80-8	Naphtha	73,960	1,000	70,761	West Manway Open - Organic Removal In Progress	Collapsed
80-9	EMPTY	76,521	0	Empty	COMPLETE - No Further Action Required	Collapsed
80-10	Pygas	74,767	900	14,382	Degassing; Organic removal in progress	Erect, fixed roof in tact
80-11	Base Oil	76,208	20,000	52,902	Organic Removal In Progress	Erect, charred, and damage to roof
80-12	EMPTY	76,502	0	Empty	COMPLETE - No Further Action Required	Partially Collapsed
80-13	Toluene	70,523	1,400	14,725	Degassing	Erect, fixed roof in tact
80-14	Pygas	72,965	100	15,840	Degassing; Sludge in tank	Collapsed
80-15	Pygas	74,692	100	9,421	Degassing; Sludge removal in progress	Collapsed
		1,110,502	26,200	470,595		

	Full of Product / No action	EMPTY	No organics in the tank
	Heel / Residual Remaining - In Process	Clean	Tank has no organics and has been rinsed and cleaned
	Cleaning or Degas	Ready to Clean	Product removed, man ways open, and ready for tank cleaning to begin
	COMPLETE - No Further Action Required		